

Agriplace and Marquis Industrial Recommended Improvements

Item	Location	Recommendation	Reason
1	Marquis Drive and Siemens Avenue	Install reflective tape on tapered end of median	Improve visibility of median
2	Millar Avenue (60 th Street to 64 th Street)	Speed display board for northbound traffic	Reduce speed
		Send speed data to Saskatoon Police Service to consider for enforcement	
3	Millar Avenue and 60 th Street	Active Pedestrian Corridor on north leg	Improve pedestrian safety
4	Millar Avenue and 64 th Street	Active Pedestrian Corridor on north leg	Improve pedestrian safety
5	East side of Kinnear Avenue (north of Silverwood Golf Course)	Sidewalk and ramps to be installed as per the Sidewalk Infill Program	Improve pedestrian safety
6	South side of Kinnear Place (east of Kinnear Avenue)		

For comments & information, visit:

www.saskatoon.ca/NTR

www.saskatoon.ca/engage/agriplace-and-marquis-industrial