



**TYPICAL SEWER SERVICE
CLEANOUT ON LONG
CONNECTION**



**TYPICAL SEWER SERVICE
CLEANOUT AT SHARP BEND**



NOTE
BACKFILL UNDER CLEANOUT
RISER TO BE 95% OF STANDARD
PROCTOR DENSITY.

REVISIONS	
1	RBY 02/08/2000
2	
3	

DRAWN BY E.D.N.
DATE APR. 1, 1992

CHECKED BY _____
DATE _____



TYPICAL SEWER SERVICE CLEANOUT

APPROVED

A. Boyko
GENERAL MANAGER P. ENG.

ENGINEER _____

ENGINEER _____

SCALES: HOR. N.T.S. VERT. _____

08025-6 PLAN NO. 102-0013-005r001