## **Nutana Park Neighbourhood Recommended Improvements**

Item	Location	Recommendation	Reason
1	Irvine Avenue & Bute Street	Install yield sign on Bute Street assigning right-of-way to Irvine Avenue	Improve intersection safety
	Irvine Avenue & Cascade Street	Install yield signs on Irvine Avenue assigning right-of-way to Cascade Street	
	Irvine Avenue & Hanson Street	Install yield signs on Hanson Street assigning right-of-way to Irvine Avenue	
	Jarvis Drive & Landa Street	Install yield sign on Landa Street assigning right-of-way to Jarvis Drive	
	Jarvis Drive & Paul Crescent	Install yield sign on Paul Crescent assigning right-of-way to Jarvis Drive	
	Jarvis Drive & Estey Drive	Install yield sign on Estey Drive assigning right-of-way to Jarvis Drive	
	Estey Drive & Paul Crescent	Install yield sign on Paul Crescent assigning right-of-way to Estey Drive	
	Jarvis Drive & Clinkskill Drive	Install yield sign on Clinkskill Drive assigning right-of-way to Jarvis Drive	
	Clinkskill Drive & Bell Crescent (North)	Install yield sign on Bell Crescent (North) assigning right-of-way to Clinkskill Drive	
	Clinkskill Drive & Bell Crescent (South)	Install yield sign on Bell Crescent (South) assigning right-of-way to Clinkskill Drive	
	Clinkskill Drive & Drinkle Street	Install yield sign on Drinkle Street assigning right-of-way to Clinkskill Drive	
	Jarvis Drive & Woodward Avenue	Install yield sign on Woodward Avenue assigning right-of-way to Jarvis Drive	
	Woodward Avenue & Guppy Street	Install yield sign on Guppy Street assigning right-of-way to Woodward Avenue	
2	Cascade Street & Estey Drive	Install standard crosswalk on north leg across Estey Drive	Improve pedestrian safety
		Relocate yield sign to Cascade Street assigning right-of-way to Estey Drive	Improve intersection safety
3	Estey Drive Back Lane (Estey Drive to Jarvis Drive)	Install "No Parking" signs along back lane	Improve compliance with bylaw
4	Jarvis Drive at Estey Drive Back Lane	Prohibit parking on the south side of Jarvis Drive 6 metres west of back lane and 3 metres east of back lane	Improve sight lines
5	Ruth Street & Jarvis Drive	Install median island on east leg on Ruth Street	Improve intersection safety

Item	Location	Recommendation	Reason
6	Louise Avenue & Murphy Crescent (North) / Ruth Street	Install median island on east leg on Louise Avenue	Reduce speed
7	Louise Avenue & Woodward Avenue	Install curb extensions on north and south sides of west crosswalk	Reduce speed
		Remove standard crosswalk on east leg	Encourage pedestrians to cross on west leg
8	Clinkskill Drive & Bell Crescent (South)	Install median island on south leg	Reduce speed
		Prohibit parking on Clinkskill Drive 15 metres from Bell Crescent (South)	Improve sight lines
9	Louise Avenue [Murphy Crescent (North) to Murphy Crescent (South)]  Louise Avenue [Murphy Crescent (South) to Woodward Avenue]  Woodward Avenue (Louise Avenue to Guppy Street)  Clinkskill Drive [Bell Crescent (North) to Bell Crescent (South)]  Wilson Crescent [Middleton Crescent to Riel Crescent (West)]  Estey Drive (Hanson Street to Drinkle Street)	Send speed data to Saskatoon Police Service for enforcement	Reduce speed
10	Various	Install missing pedestrian accessibility ramps (80 in total)	Improve pedestrian accessibility

You can provide comments online at <a href="https://www.saskatoon.ca/engage">www.saskatoon.ca/engage</a>