

Appendix A

Inspection Reports and Photos

General Photos

2010 Traffic Bridge Inspection



Photo 3
Typical railing, LHS



Photo 4
Typical railing RHS

2010 Traffic Bridge Inspection



Photo 5

Typical deck wearing surface - Note light wheel track rutting, light raveling and light flushing



Photo 6

Typical shot of vertical, RHS

2010 Traffic Bridge Inspection



Photo 7
Typical shot of diagonals



Photo 8
Typical shot of top chord

2010 Traffic Bridge Inspection



Photo 9

Typical shot of top chord bracing



Photo 10

Typical shot of portal bracing

2010 Traffic Bridge Inspection



Photo 11
Deck joint at pier 2



Photo 12
Typical shot facing downstream

2010 Traffic Bridge Inspection



Photo 13
Typical shot facing upstream



Photo 14
Joint at pier 4

2010 Traffic Bridge Inspection



Photo 15
General Approach from the north facing south



Photo 16
Typical shot of pedestrain rail

2010 Traffic Bridge Inspection



Photo 17
Elevation from upstream



Photo 18
Elevation from downstream

2010 Traffic Bridge Inspection



Photo 19
Typical shot of pier 2



Photo 20
Typical shot of pier 1

2010 Traffic Bridge Inspection



Photo 21
Typical shot bottom chord



Photo 22
Typical shot of floor beam stringers and bottom chord bracing

2010 Traffic Bridge Inspection



Photo 23

Typical shot of pedestrian floor beams and stringers