

A photograph of a construction worker in a trench. The worker is wearing a yellow hard hat, an orange safety vest, and black rubber boots. They are standing in a deep, muddy trench next to a wooden retaining wall. A white pipe is visible in the trench. The text "Sanitary Sewer Connection Repair Presentation Resources" is overlaid on the image.

Sanitary Sewer Connection Repair Presentation Resources




People

1 – Supervisor IV



2 - Labourers




1 - Backhoe operator



2 - Tandem axle truck operators



1 - Loader operator (as required)



A photograph of a construction or maintenance site. A worker wearing a yellow hard hat, an orange high-visibility vest, and black rubber boots is kneeling in a dirt trench. A white pipe with a black cap is lying horizontally across the trench. A shovel with a wooden handle and a metal head is positioned vertically next to the pipe. The trench is dug into brown soil, and a wooden fence is visible in the background. The word "Equipment" is overlaid in the center of the image.

Equipment

Feeling Rod



Tunnelling Shovel



Shovel



Broom



Scraper



Rasp / File



Nut Driver



Flathead Screwdriver



Sledge Hammer



Pick Axe



Disinfectant Sprayer



Asphalt/Concrete Saw



Quickie Saw



Tile Cutter



Crew Trailer



Excavator/Backhoe



Shoring & Trailer



Truck



Front End Loader



Hydraulic Tamper



Vibratory Compactor



Handheld Plate Tamper



Hacksaw





Materials

PVC Sewer Connection Pipe



Straight Coupler



Transition Coupler



Short 22.5° Elbow



Long 22.5° Elbow



Short 45° Elbow



Long 45° Elbow



Treated Block




Cleaning Rags



Service Saddle



A construction worker wearing a yellow hard hat and an orange safety vest is kneeling in a dirt trench. A white pipe with a black cap lies on the ground next to the worker. A shovel is also visible in the trench. The background shows a wooden fence.

Thank You.
Are there any Questions?